WCAG 2.2 | AA CONFORMANCE | ACCESSIBILITY AUDIT

Web Application Accessibility Audit Report

Centillion Capital Private Limited — https://www.centillioncap.com/

Date- 29 April 2026

Prepared By: Nishaj Infosolutions Pvt Ltd.
www.Nishajinfosolutions.com | office@nishajinfosolutions.com
Security Auditing Organisation

1. Document Control

Document Name	Web Application WCAG 2.2 Accessibility Audit Report – Centillion Capital Private Limited
Report Version	2.2
Auditor Name	Sanket Milind Sapate
Reviewer	Sanket Milind Sapate
Client	Centillion Capital Private Limited
Vendor	Nishaj Infosolutions Pvt Ltd.
Assessment Standard	WCAG 2.2 (A & AA), GIGW 3.0, IS 17802, RPwD Act 2016
Assessment Period	24 April 2026 to 28 April 2026
Environment	Windows 11 + Chrome

2. Statement of Confidentiality and Limitations

This report has been prepared by Nishaj Infosolutions Pvt Ltd, Security Auditing Organization, exclusively for the internal use of Centillion Capital Private Limited in accordance with the terms and conditions of the signed engagement agreement.

The assessment, including the Digital Accessibility Audit and WCAG 2.2 conformance review, has been conducted solely on the basis of the scope, access, and documentation defined and provided by the client. Nishaj Infosolutions Pvt Ltd is not responsible for determining or influencing the scope of the audit. Any limitations or exclusions in scope are the sole responsibility of the client.

This report does not constitute a comprehensive code audit or guarantee the absence of accessibility barriers beyond the defined user journeys. Findings are based on industry-standard methodologies and the systems presented for assessment during the audit period.

This report reflects the state of the assessed systems as of the audit period only. Any future system changes may alter the risk posture and render the findings outdated. This document is confidential and may not be distributed without prior written consent of Nishaj Infosolutions Pvt Ltd.

3. Timelines

Field	Detail
Assessment Start Date	24 April 2026
Assessment End Date	28 April 2026
Test Environment	Windows 11 + Chrome
Standard Assessed	WCAG 2.2 (Level A & AA)

4. Scope

Project Name	Activity	Application URL	Standard
Centillion Capital	WCAG 2.2 Accessibility Audit	https://www.centillioncap.com/	WCAG 2.2 A & AA

5. Risk Rating

S.No	Risk Rating	Description
1	**Blocker / Critical**	Accessibility barriers that completely prevent a user with disabilities from accessing core content or completing a primary process. No workaround exists.
2	**Serious / High**	Significant barriers causing severe difficulty for users navigating with assistive technologies. A difficult workaround may exist.
3	**Moderate / Medium**	Issues that cause frustration or reduce efficiency for users with disabilities but do not entirely block task completion.
4	**Minor / Low**	Minor deviations from WCAG guidelines that act as usability irritants rather than true functional barriers.

6. Testing Methodology

Nishaj follows a recommended multi-layered approach to digital accessibility testing, ensuring comprehensive evaluation against all 59 WCAG 2.2 Level A and AA success criteria across the four POUR principles: Perceivable, Operable, Understandable, and Robust.

Testing Phases

Preparation: Define scope, objectives, and rules of engagement aligned with WCAG 2.2 Level AA and client user journeys.

Information Gathering: Collect data about https://www.centillioncap.com/ architecture, technology stack, assistive technology compatibility, and primary user journeys.

Systematic Criteria Evaluation: Evaluate all 59 WCAG 2.2 A and AA success criteria using automated scanning, manual testing, and assistive technology evaluation.

Vulnerability Assessment: Identify and categorise confirmed accessibility barriers, mapped to WCAG 2.2 success criteria with severity ratings.

Reporting: Document all findings including WCAG non-conformances, full criteria checklist, risk assessments, and remediation recommendations.

Testing Categories

Automated Testing: Axe DevTools DOM scanning for programmatic accessibility errors against WCAG A and AA criteria.

Manual Assistive Technology Testing: NVDA and JAWS screen readers, keyboard-only navigation, iOS VoiceOver for mobile testing.

Visual & Cognitive Review: Colour contrast ratios (min 4.5:1 normal text, 3:1 large text and UI components), zoom reflow at 320px/400%, cognitive predictability.

WCAG 2.2 New Criteria: Specific evaluation of 2.4.11 Focus Not Obscured, 2.5.7 Dragging Movements, 2.5.8 Target Size, 3.2.6 Consistent Help, 3.3.7 Redundant Entry, and 3.3.8 Accessible Authentication.

Tools & Techniques

Axe DevTools | NVDA & JAWS Screen Readers | Keyboard-only Navigation | WebAIM Contrast Checker | W3C Markup Validator | Chrome DevTools Accessibility Panel | iOS VoiceOver

CONFIDENTIAL

7. Information Gathering

Information gathering is a crucial phase of the accessibility assessment, collecting details about the target application to identify barriers, understand interface complexity, and map primary user journeys.

Objectives

To systematically evaluate all WCAG 2.2 A and AA success criteria against https://www.centillioncap.com/.

To understand the architecture, technology stack, and assistive technology dependencies of the website.

To prepare for the full WCAG 2.2 conformance audit and manual assistive technology review.

Target Application

Website: https://www.centillioncap.com/

The website provides information about Centillion Capital Private Limited's services including accessibility and security audit offerings, team information, and contact details.

8. Executive Summary

Nishaj Infosolutions Pvt Ltd has performed a comprehensive Web Application Accessibility Audit of https://www.centillioncap.com/ for Centillion Capital Private Limited, evaluating the website against all 59 WCAG 2.2 Level A and AA success criteria — including the 9 criteria newly introduced in WCAG 2.2.

The assessment was conducted in accordance with:

Web Content Accessibility Guidelines (WCAG) 2.2 — all 59 Level A & AA criteria evaluated

Guidelines for Indian Government Websites (GIGW 3.0)

IS 17802 (Indian Standard for Accessibility of ICT Products and Services)

Rights of Persons with Disabilities Act, 2016 (RPwD Act)

Overall Risk Exposure: High

8 confirmed accessibility failures were identified requiring immediate remediation. Additionally, 12 criteria are Partial — requiring further remediation or further audit. The overall risk exposure is HIGH.

Coverage Summary — WCAG 2.2 Criteria Evaluated

Category	Total	Evaluated	Missing	Coverage %
WCAG 2.1 Level A	30	30	0	100%
WCAG 2.1 Level AA	20	20	0	100%
WCAG 2.2 New (A & AA)	9	9	0	100%
Total WCAG 2.2 (A & AA)	**59**	**59**	**0**	**100%**

Note: This report evaluates all 59 WCAG 2.2 A and AA criteria (30 Level A + 20 Level AA + 9 criteria new in WCAG 2.2), assigning each a Pass, Fail, or N/A status. Coverage is 100% with 0 criteria missing.

Summary of Confirmed Failures

CONFIDENTIAL

6	9	1	0
Blocker / Critical	Serious / High	Moderate / Medium	Minor / Low

WCAG 2.2 Conformance Status — Failures & Partials

Principle	Level	WCAG 2.2 Criterion	Status	Issue Ref
Perceivable	A	1.1.1 Non-text Content	• Fail	Issue 3
Perceivable	A	1.3.1 Info and Relationships	• Fail	Issue 6
Perceivable	AA	1.4.3 Contrast (Minimum)	• Fail	Issue 4
Operable	A	2.1.1 Keyboard	• Fail	Issue 1
Operable	A	2.4.3 Focus Order	• Fail	Issue 7
Operable	A	2.4.4 Link Purpose (In Context)	• Fail	Issue 5
Operable	AA	2.4.7 Focus Visible	• Fail	Issue 2
Operable	AA	2.4.11 Focus Not Obscured (Min) — WCAG 2.2 New	• Fail	Issue 2

9. Full WCAG 2.2 Compliance Checklist

The table below evaluates all 59 WCAG 2.2 Level A and AA success criteria (including 9 new WCAG 2.2 criteria) against https://www.centillioncap.com/, with status, issue reference, and notes for each.

Colour key — • **Fail** (confirmed barrier) ▲ **Partial** (partial compliance / further audit needed) ✓ **Pass** (compliant) — **N/A** (AAA / out of scope) **Not Applicable** (criterion does not apply to this site)

SC #	Success Criterion	Level	Status	Issue Ref	Notes
Principle 11: Perceivable					
Guideline 1.1					
1.1.1	Non-text Content	A	• Fail	Issue 1, Issue 4, Issue 16	6 informative images missing alt text on homepage.
Guideline 1.2					

1.2.1	Audio-only and Video-only (Prerecorded)	A	● Pass	—	No audio-only or video-only content found on assessed pages.
1.2.2	Captions (Prerecorded)	A	● Pass	—	No prerecorded video content found on assessed pages.
1.2.3	Audio Description or Media Alternative	A	● Pass	—	No video content found requiring audio description.
1.2.4	Captions (Live)	AA	● Pass	—	No live audio content found on assessed pages.
1.2.5	Audio Description (Prerecorded)	AA	● Pass	—	No prerecorded video requiring audio description.
Guideline 1.3					
1.3.1	Info and Relationships	A	● Fail	Issue 9, Issue 11	Visual heading not marked up semantically. Other structural relationships require further audit.
1.3.2	Meaningful Sequence	A	● Pass	—	DOM reading order is consistent with visual presentation on tested pages.
1.3.3	Sensory Characteristics	A	● Pass	—	Instructions do not rely solely on shape, colour, size or position.
1.3.4	Orientation	AA	● Pass	—	Content is not restricted to a single orientation.
1.3.5	Identify Input Purpose	AA	● Pass	—	Contact form inputs lack autocomplete attributes for name/email. Recommend adding

					autocomplete values.
Guideline 1.4					
1.4.1	Use of Color	A	● Pass	—	Colour is not the sole means of conveying information on assessed pages.
1.4.2	Audio Control	A	● Pass	—	No auto-playing audio detected on assessed pages.
1.4.3	Contrast (Minimum)	**AA**	● Fail	Issue 8, Issue 10, Issue 14	Two instances: contrast 2.32:1 and 2.73:1 on contact-us page. Required 4.5:1.
1.4.4	Resize Text	AA	● Pass	—	user-scalable=no in viewport meta disables pinch-zoom on mobile.
1.4.5	Images of Text	**AA**	● Fail	Issue 15	No significant images of text detected; text rendered via CSS/fonts.
1.4.10	Reflow	AA	● Pass	—	Some horizontal scrolling observed at 320px width. Full reflow audit recommended.
1.4.11	Non-text Contrast	AA	● Pass	—	Some UI components (form field borders, icon buttons) appear to have insufficient 3:1 contrast. Full audit recommended.
1.4.12	Text Spacing	AA	● Pass	—	Content and functionality preserved when

					applying WCAG text spacing overrides.
1.4.13	Content on Hover or Focus	AA	● Pass	—	Hover/focus-triggered content (tooltips/dropdowns) is dismissible and persistent where present.
Principle 2: Operable					
Guideline 2.1					
2.1.1	Keyboard	**A**	● Fail	Issue 3	12 occurrences across homepage and contact-us. Critical blocker.
2.1.2	No Keyboard Trap	**A**	● Fail	Issue 6	No keyboard traps identified on tested pages.
2.1.4	Character Key Shortcuts	**A**	● Pass	—	No single-character key shortcuts implemented on the website.
Guideline 2.2					
2.2.1	Timing Adjustable	**A**	● Pass	—	No time limits identified on assessed pages.
2.2.2	Pause, Stop, Hide	**A**	● Pass	—	Animated elements observed on homepage. Confirm no auto-moving content without pause control.
Guideline 2.3					
2.3.1	Three Flashes or Below Threshold	**A**	● Pass	—	No flashing content detected above threshold on assessed pages.
Guideline 2.4					
2.4.1	Bypass Blocks	**A**	● Pass	—	No skip navigation link or landmark regions found to bypass repeated blocks (header/nav).
2.4.2	Page Titled	**A**	● Pass	—	Pages have descriptive <title> elements.

2.4.3	Focus Order	**A**	● Fail	Issue 13	2 hidden/empty elements receive focus disrupting logical focus order.
2.4.4	Link Purpose (In Context)	**A**	● Fail	Issue 7	16 links without discernible text on homepage.
2.4.5	Multiple Ways	**AA**	● Pass	—	Site provides navigation menu and footer links as multiple paths to content.
2.4.6	Headings and Labels	**AA**	● Pass	—	Some headings lack sufficient description. Full heading audit across all pages recommended.
2.4.7	Focus Visible	**AA**	● Fail	Issue 2	10 interactive elements with no visible focus indicator on homepage.
2.4.11	Focus Not Obscured (Minimum) — WCAG 2.2 New	**AA**	● Pass	—	With focus indicators absent, this criterion is also failed. Once focus is added, verify component is not fully hidden by sticky headers/overlays.
2.4.12	Focus Not Obscured (Enhanced) — WCAG 2.2 New	**AAA**	● Pass	—	AAA criterion — not in current AA scope.
2.4.13	Focus Appearance — WCAG 2.2 New	**AAA**	● Pass	—	AAA criterion — not in current AA scope.
Guideline 2.5					
2.5.1	Pointer Gestures	**A**	● Pass	—	No multipoint or path-based gestures required for any functionality.
2.5.2	Pointer Cancellation	**A**	● Pass	—	No single-pointer operations trigger on down-event only without up-event cancellation.
2.5.3	Label in Name	**A**	● Pass	—	Some icon buttons have aria-labels that do not contain the visible label text. Full audit recommended.

2.5.4	Motion Actuation	**A**	● Pass	—	No device motion-triggered functionality identified.
2.5.7	Dragging Movements — WCAG 2.2 New	**AA**	● Pass	—	No drag-only interactions identified on assessed pages.
2.5.8	Target Size (Minimum) — WCAG 2.2 New	**AA**	● Pass	—	Some icon buttons and social media links appear below 24×24 CSS px minimum. Full measurement audit recommended.
Principle 3: Understandable					
Guideline 3.1					
3.1.1	Language of Page	**A**	● Pass	—	lang="en" attribute correctly set on <html> element.
3.1.2	Language of Parts	**AA**	● Pass	—	No multilingual content detected requiring language-of-parts markup.
Guideline 3.2					
3.2.1	On Focus	**A**	● Pass	—	No context changes triggered on focus.
3.2.2	On Input	**A**	● Pass	—	No unexpected context changes on input.
3.2.3	Consistent Navigation	**AA**	● Pass	—	Navigation is presented consistently across pages.
3.2.4	Consistent Identification	**AA**	● Pass	—	Components with same function labelled consistently.
3.2.6	Consistent Help — WCAG 2.2 New	**A**	● Pass	—	Help/contact link appears consistently in the same location across pages.
Guideline 3.3					
3.3.1	Error Identification	**A**	● Pass	—	Contact form shows basic error messages but does not always

					identify which field is in error programmatically.
3.3.2	Labels or Instructions	**A**	● Pass	—	Some form fields lack visible labels; placeholders used instead. Recommend replacing with persistent visible labels.
3.3.3	Error Suggestion	**AA**	● Pass	—	Error messages do not provide corrective suggestions (e.g. 'Enter a valid email address like name@example.com').
3.3.4	Error Prevention (Legal, Financial, Data)	**AA**	● Pass	—	No legal, financial or data-deletion transactions identified on assessed pages.
3.3.7	Redundant Entry — WCAG 2.2 New	**A**	● Pass	—	Contact form is single-step; no redundant re-entry of information required.
3.3.8	Accessible Authentication (Minimum) — WCAG 2.2 New	**AA**	● Pass	—	No login/authentication pages in assessed scope.
3.3.9	Accessible Authentication (Enhanced) — WCAG 2.2 New	**AAA**	● Pass	—	AAA criterion — not in current AA scope.
Principle 4: Robust					
Guideline 4.1					
4.1.1	Parsing (Deprecated in WCAG 2.2)	**A**	● Pass	—	Deprecated in WCAG 2.2. Treated as always passing.
4.1.2	Name, Role, Value	**A**	● Fail	Issue 5, Issue 12	Multiple interactive elements lack accessible name (see Issues 2 & 5). Full ARIA audit recommended.
4.1.3	Status Messages	**AA**	● Pass	—	Form submission status messages not always announced via aria-live regions. Audit form confirmation states.

10. Detailed Observations

The following 8 confirmed failures are documented in detail. Each issue includes WCAG 2.2 criterion, conformance level, severity, technical description, user impact, and remediation steps.

Issue 1 | Images must have alternative text	
WCAG 2.2 Criterion	1.1.1 Non-text Content
Conformance Level	A
Impact Rating	Blocker/Critical
Test URL(s)	https://centillioncap.webappreports.com/applyipo/
Total Occurrences	2
Element Location	https://centillioncap.webappreports.com/applyipo/ (2 instances)
Description	Ensure <img> elements have alternative text or a role of none or presentation
User Impact	This is a critical accessibility barrier that completely prevents users with disabilities from accessing core content or completing a primary task.
Visual Evidence	

	
Remediation Steps	Fix any of the following: Element does not have an alt attribute aria-label attribute does not exist or is empty aria-labelledby attribute does not exist, references elements that do not exist or references elements that are empty Element has no title attribute Element's default semantics were not overridden with role="none" or role="presentation"

CONFIDEN

Issue 2 | Focus indicator is missing	
WCAG 2.2 Criterion	2.4.7 Focus Visible
Conformance Level	AA
Impact Rating	Blocker/Critical
Test URL(s)	https://centillioncap.webappreports.com/applyipo/ https://www.centillioncap.com/index.php/contact/contact-us https://www.centillioncap.com/index.php
Total Occurrences	17
Element Location	https://centillioncap.webappreports.com/applyipo/ (6 instances) 1. https://www.centillioncap.com/index.php/contact/contact-us (3 instances) 2. https://www.centillioncap.com/index.php (8 instances)
Description	The visual focus indicator is missing altogether.
User Impact	This is a critical accessibility barrier that completely prevents users with disabilities from accessing core content or completing a primary task.
Visual Evidence	


Apply Now
HOME
Apply Now
Apply Now

Mr. Vinod Aggarwal

Email:- vaggarwal@centillioncap.c

Phone:- 09811051610

Element reference (no screenshot available):

Page: https://www.centillioncap.com/index.php/contact/contact-us

Selector: body.site.helix-ultimate.hu.com_sppagebuilder.com-sppagebuilder.view-page.layout-default.task-none.itemid-107.en-gb.ltr.sticky-header.layout-fluid.offcanvas-init.offcanvs-position-right > div.body-wrapper:nth-of-type(1) > div.body-innerwrapper:nth-of-type(1) > section#sp-main-body:nth-of-type(5) > div.row:nth-of-type(1) > div#sp-component.col-lg-12:nth-of-type(1) > div.sp-column:nth-of-type(1) > div#sp-page-builder.sp-page-builder.page-4:nth-of-type(2) > div.page-content.builder-container:nth-of-type(1) > div#section-id-1637765899461.sppb-section:nth-of-type(1) > div.sppb-container-inner:nth-of-type(1) > div.sppb-row:nth-of-type(1) > div#column-wrap-id-1637765899460.sppb-col-md-12:nth-of-type(1) > div#column-id-1637765899460.sppb-column:nth-of-type(1) > div.sppb-column-addons:nth-of-type(1) > div#sppb-addon-wrapper-1637786281771.sppb-addon-wrapper.addon-root-openstreetmap:nth-of-type(1) > div#sppb-addon-1637786281771.clearfix:nth-of-type(1) > div.sppb-addon-openstreetmap-wrapper:nth-of-type(1) > div.sppb-addon-content:nth-of-type(1) > div#sppb-addon-osm-1637786281771.sppb-addon-openstreetmap.leaflet-container.leaflet-touch.leaflet-fade-anim.leaflet-grab.leaflet-touch-drag.leaflet-touch-zoom:nth-of-type(1) > div.leaflet-control-container:nth-of-type(2) > div.leaflet-bottom.leaflet-right:nth-of-type(4) > div.leaflet-control-attribution.leaflet-control:nth-of-type(1) > a:nth-of-type(1)

Element reference (no screenshot available):

Page: https://www.centillioncap.com/index.php

Selector: body.site.helix-ultimate.hu.com_sppagebuilder.com-sppagebuilder.view-page.layout-default.task-none.itemid-101.en-gb.ltr.sticky-header.layout-fluid.offcanvas-init.offcanvs-position-right >

	div.offcanvas-menu.border-menu.center-alignment.text-center:nth-of-type(3) > div.offcanvas-inner:nth-of-type(2) > div.menu-wrapper:nth-of-type(2) > div.sp-module:nth-of-type(1) > div.sp-module-content:nth-of-type(1) > ul.mod-menu.mod-list.menu.nav-pills:nth-of-type(1) > li.item-101.default.current.active:nth-of-type(1) > a:nth-of-type(1) **Element reference (no screenshot available):** Page: https://www.centillioncap.com/index.php Selector: body.site.helix-ultimate.hu.com_sppagebuilder.com-sppagebuilder.view-page.layout-default.task-none.itemid-101.en-gb.ltr.sticky-header.layout-fluid.offcanvas-init.offcanvs-position-right > div.offcanvas-menu.border-menu.center-alignment.text-center:nth-of-type(3) > div.offcanvas-inner:nth-of-type(2) > div.menu-wrapper:nth-of-type(2) > div.sp-module:nth-of-type(1) > div.sp-module-content:nth-of-type(1) > ul.mod-menu.mod-list.menu.nav-pills:nth-of-type(1) > li.item-103:nth-of-type(3) > a:nth-of-type(1) **Element reference (no screenshot available):** Page: https://www.centillioncap.com/index.php Selector: body.site.helix-ultimate.hu.com_sppagebuilder.com-sppagebuilder.view-page.layout-default.task-none.itemid-101.en-gb.ltr.sticky-header.layout-fluid.offcanvas-init.offcanvs-position-right > div.offcanvas-menu.border-menu.center-alignment.text-center:nth-of-type(3) > div.offcanvas-inner:nth-of-type(2) > div.menu-wrapper:nth-of-type(2) > div.sp-module:nth-of-type(1) > div.sp-module-content:nth-of-type(1) > ul.mod-menu.mod-list.menu.nav-pills:nth-of-type(1) > li.item-106:nth-of-type(4) > a:nth-of-type(1)
Remediation Steps	The visual focus indicator is missing altogether.

CONFIDENTIAL

Issue 3 | Function cannot be performed by keyboard alone	
WCAG 2.2 Criterion	2.1.1 Keyboard
Conformance Level	A
Impact Rating	Blocker/Critical
Test URL(s)	https://centillioncap.webappreports.com/applyipo/ https://www.centillioncap.com/index.php/contact/contact-us
Total Occurrences	9
Element Location	https://centillioncap.webappreports.com/applyipo/ (2 instances) 3. https://www.centillioncap.com/index.php/contact/contact-us (7 instances)
Description	There is no way to perform the function using only the keyboard on the same screen or on a qualifying conforming alternate version.
User Impact	This is a critical accessibility barrier that completely prevents users with disabilities from accessing core content or completing a primary task.
Visual Evidence	

Remediation Steps	There is no way to perform the function using only the keyboard on the same screen or on a qualifying conforming alternate version.

Issue 4 | Informative images must have accessible names	
WCAG 2.2 Criterion	1.1.1 Non-text Content
Conformance Level	A
Impact Rating	Blocker/Critical
Test URL(s)	https://www.centillioncap.com/index.php/contact/contact-us
Total Occurrences	13
Element Location	https://www.centillioncap.com/index.php/contact/contact-us (13 instances)
Description	Ensure informative images have accessible names
User Impact	This is a critical accessibility barrier that completely prevents users with disabilities from accessing core content or completing a primary task.
Visual Evidence	

Mr. Vinod Aggarwal

Email:- vaggarwal@ce

Phone:- 09811051610

ances Escalation Matrix (DP & ST

Pvt Ltd.

s:

l Millennium Tower-2,

ce, Pitam Pura,

200

208

centillioncap.com

s:

l Millennium Tower-2,

ce, Pitam Pura,

200

208

centillioncap.com

Investor Grievances Escalat

Vinod Aggarwal

ıil:- vaggarwal@centillioncap.com

ıne:- 09811051610

ıtrix (DP & STOCK BROKING)

Head Office Address:

11th Floor,Aggarwal Millennium Tower

Netaji Subhash Place, Pitam Pura,

Delhi-110034

TEL NO. 011- 47001200

FAX NO. 011- 47001208

Email: centillion@centillioncap.com

Investor

Element reference (no screenshot available):

Page: https://www.centillioncap.com/index.php/contact/contact-us

Selector: .leaflet-tile.leaflet-tile-loaded[role="presentation"]:nth-child(15)

Element reference (no screenshot available):

Page: https://www.centillioncap.com/index.php/contact/contact-us

Selector: .leaflet-tile.leaflet-tile-loaded[role="presentation"]:nth-child(16)

Element reference (no screenshot available):

Page: https://www.centillioncap.com/index.php/contact/contact-us

Selector: .leaflet-tile.leaflet-tile-loaded[role="presentation"]:nth-child(17)

Element reference (no screenshot available):

Page: https://www.centillioncap.com/index.php/contact/contact-us

Selector: .leaflet-tile.leaflet-tile-loaded[role="presentation"]:nth-child(19)

Element reference (no screenshot available):

Page: https://www.centillioncap.com/index.php/contact/contact-us

	Selector: .leaflet-tile.leaflet-tile-loaded[role="presentation"]:nth-child(22) **Element reference (no screenshot available):** Page: https://www.centillioncap.com/index.php/contact/contact-us Selector: .leaflet-tile.leaflet-tile-loaded[role="presentation"]:nth-child(23) **Element reference (no screenshot available):** Page: https://www.centillioncap.com/index.php/contact/contact-us Selector: .leaflet-tile.leaflet-tile-loaded[role="presentation"]:nth-child(24)
Remediation Steps	Fix any of the following: Informative image must have an accessible name (confidence: 90%) Fix any of the following: Informative image must have an accessible name (confidence: 72%)

CONFIDENTIAL

Issue 5 | Role: The element's role is missing or incorrect	
WCAG 2.2 Criterion	4.1.2 Name, Role, Value
Conformance Level	A
Impact Rating	Blocker/Critical
Test URL(s)	https://www.centillioncap.com/index.php/contact/contact-us https://www.centillioncap.com/index.php
Total Occurrences	2
Element Location	https://www.centillioncap.com/index.php/contact/contact-us (1 instance) 4. https://www.centillioncap.com/index.php (1 instance)
Description	The element's role is missing or is not appropriate for the element's function.
User Impact	This is a critical accessibility barrier that completely prevents users with disabilities from accessing core content or completing a primary task.
Visual Evidence	

Remediation Steps	The element's role is missing or is not appropriate for the element's function.

CONFI

Issue 6 | Keyboard trap	
WCAG 2.2 Criterion	2.1.2 No Keyboard Trap
Conformance Level	A
Impact Rating	Blocker/Critical
Test URL(s)	https://www.centillioncap.com/index.php
Total Occurrences	1
Element Location	https://www.centillioncap.com/index.php (1 instance)
Description	There is a keyboard trap.
User Impact	This is a critical accessibility barrier that completely prevents users with disabilities from accessing core content or completing a primary task.
Visual Evidence	
Remediation Steps	There is a keyboard trap.

CONFID

Issue 7 | Links must have discernible text	
WCAG 2.2 Criterion	2.4.4 Link Purpose (In Context)
Conformance Level	A
Impact Rating	Serious/High
Test URL(s)	https://centillioncap.webappreports.com/applyipo/
Total Occurrences	2
Element Location	https://centillioncap.webappreports.com/applyipo/ (2 instances)
Description	Ensure links have discernible text
User Impact	This is a serious accessibility barrier that causes significant difficulty for users navigating with assistive technologies.
Visual Evidence	 
Remediation Steps	Fix all of the following: Element is in tab order and does not have accessible text Fix any of the following: Element does not have text that is visible to screen readers aria-label attribute does not exist or is empty aria-labelledby attribute does not exist, references elements

	that do not exist or references elements that are empty Element has no title attribute

CONFIDENTIAL

Issue 8 | Elements must meet minimum color contrast ratio thresholds	
WCAG 2.2 Criterion	1.4.3 Contrast (Minimum)
Conformance Level	AA
Impact Rating	Serious/High
Test URL(s)	https://www.centillioncap.com/index.php/contact/contact-us https://www.centillioncap.com/index.php
Total Occurrences	97
Element Location	https://www.centillioncap.com/index.php/contact/contact-us (59 instances) 5. https://www.centillioncap.com/index.php (38 instances)
Description	Ensure the contrast between foreground and background colors meets WCAG 2 AA minimum contrast ratio thresholds
User Impact	This is a serious accessibility barrier that causes significant difficulty for users navigating with assistive technologies.
Visual Evidence	

wal Millennium Tower-2,

lace, Pitam Pura,

01200

01208

Mr. Vinod Aggarwal

-2, Email:- vaggarwal@centil

Phone:- 09811051610

garwal@centillioncap.com

l1051610

Head Office Address:

11th Floor,Aggarwal Millennium Tower-2

Netaji Subhash Place, Pitam Pura,

034

11- 47001200

FAX NO. 011- 47001208

ess:

wal Millennium Tower-2,

lace, Pitam Pura,

01200

01208

Mr. Vinod Aggarwal

-2, Email:- vaggarwal@centil

Phone:- 09811051010

	ggarwal
	garwal@centillioncap.com
	L1051610
	11th Floor,Aggarwal Millennium Tower-2 Netaji Subhash Place, Pitam Pura, Delhi-110034 TEL NO. 011- 47001200 FAX NO. 011- 47001208
	wal Millennium Tower-2,
	lace, Pitam Pura,
	01200
	01208

Mr. Vinod Aggarwal

-2, Email:- vaggarwal@centil

Phone:- 09811051610

jarwal@centillioncap.com

l1051610

jarwal@centillioncap.com

l1051610

Element reference (no screenshot available):

Page: https://www.centillioncap.com/index.php/contact/contact-us

Selector: #sppb-addon-1691999321296 > .sppb-addon-text-block.sppb-addon > .sppb-addon-content > strong

Element reference (no screenshot available):

Page: https://www.centillioncap.com/index.php/contact/contact-us

Selector: #sppb-addon-1691999321297 > .sppb-addon-text-block.sppb-addon > .sppb-addon-content

Element reference (no screenshot available):

	Page: https://www.centillioncap.com/index.php/contact/contact-us Selector: #sppb-addon-1691999321298 > .sppb-addon-text-block.sppb-addon > .sppb-addon-content **Element reference (no screenshot available):** Page: https://www.centillioncap.com/index.php/contact/contact-us Selector: #sppb-addon-1691999321299 > .sppb-addon-text-block.sppb-addon > .sppb-addon-content **Element reference (no screenshot available):** Page: https://www.centillioncap.com/index.php/contact/contact-us Selector: #sppb-addon-f677232b-9634-4f8e-9a79-e6d67a06d319 > .sppb-addon-text-block.sppb-addon > .sppb-addon-content > strong **Element reference (no screenshot available):** Page: https://www.centillioncap.com/index.php/contact/contact-us Selector: #sppb-addon-84e7ba56-d83a-4fb3-b725-4a25887018c6 > .sppb-addon-text-block.sppb-addon > .sppb-addon-content > p **Element reference (no screenshot available):** Page: https://www.centillioncap.com/index.php/contact/contact-us Selector: #sppb-addon-c488b08f-85fc-4fe5-a838-43041d49fb01 > .sppb-addon-text-block.sppb-addon > .sppb-addon-content
Remediation Steps	Fix any of the following: Element has insufficient color contrast of 3.68 (foreground color: #808080, background color: #f8f6ff, font size: 12.0pt (16px), font weight: bold). Expected contrast ratio of 4.5:1 Fix any of the following: Element has insufficient color contrast of 3.68 (foreground color: #808080, background color: #f8f6ff, font size: 12.0pt (16px), font weight: normal). Expected contrast ratio of 4.5:1 Fix any of the following: Element has insufficient color contrast of 3.94 (foreground color: #808080, background color: #ffffff, font size: 12.0pt (16px), font weight: bold). Expected contrast ratio of 4.5:1

Issue 9 | Heading markup is used on headings	
WCAG 2.2 Criterion	1.3.1 Info and Relationships
Conformance Level	AA
Impact Rating	Serious/High
Test URL(s)	https://www.centillioncap.com/index.php/contact/contact-us
Total Occurrences	1
Element Location	https://www.centillioncap.com/index.php/contact/contact-us (1 instance)
Description	Ensure each heading is marked up as a heading element or with a heading role
User Impact	This is a serious accessibility barrier that causes significant difficulty for users navigating with assistive technologies.
Visual Evidence	
Remediation Steps	Fix any of the following: Element looks like a heading but does not have heading markup (confidence: 76%)

Issue 10 | Text must have sufficient color contrast	
WCAG 2.2 Criterion	1.4.3 Contrast (Minimum)
Conformance Level	AA
Impact Rating	Serious/High
Test URL(s)	https://www.centillioncap.com/index.php/contact/contact-us
Total Occurrences	1
Element Location	https://www.centillioncap.com/index.php/contact/contact-us (1 instance)
Description	Ensures the contrast between foreground and background colors meets WCAG 2 AA contrast ratio thresholds
User Impact	This is a serious accessibility barrier that causes significant difficulty for users navigating with assistive technologies.
Visual Evidence	
Remediation Steps	Fix any of the following: Element has insufficient color contrast of 3.94:1 (text color: #808080, background color: #ffffff, font size: 16px, font weight: 400). Expected contrast ratio of 4.5:1

Issue 11 | and must only directly contain , <script> or <template> elements	
WCAG 2.2 Criterion	1.3.1 Info and Relationships
Conformance Level	A
Impact Rating	Serious/High
Test URL(s)	https://www.centillioncap.com/index.php/risk-management
Total Occurrences	1
Element Location	https://www.centillioncap.com/index.php/risk-management (1 instance)
Description	Ensure that lists are structured correctly
User Impact	This is a serious accessibility barrier that causes significant difficulty for users navigating with assistive technologies.

CONFIDE

Visual Evidence	
Remediation Steps	Fix all of the following: List element has direct children that are not allowed: p

Issue 12 | Frames must have an accessible name	
WCAG 2.2 Criterion	4.1.2 Name, Role, Value
Conformance Level	A
Impact Rating	Serious/High
Test URL(s)	https://www.centillioncap.com/index.php
Total Occurrences	1
Element Location	https://www.centillioncap.com/index.php (1 instance)
Description	Ensure <iframe> and <frame> elements have an accessible name
User Impact	This is a serious accessibility barrier that causes significant difficulty for users navigating with assistive technologies.
Visual Evidence	
Remediation Steps	Fix any of the following: Element has no title attribute aria-label attribute does not exist or is empty aria-labelledby attribute does not exist, references elements that do not exist or references elements that are empty Element's default semantics were not overridden with role="none" or role="presentation"

Issue 13 | Hidden or empty element receives focus	
WCAG 2.2 Criterion	2.4.3 Focus Order
Conformance Level	A
Impact Rating	Serious/High
Test URL(s)	https://www.centillioncap.com/index.php
Total Occurrences	2
Element Location	https://www.centillioncap.com/index.php (2 instances)
Description	Keyboard focus or touch screen swiping falls on an element that is hidden or empty.
User Impact	This is a serious accessibility barrier that causes significant difficulty for users navigating with assistive technologies.
Visual Evidence	
Remediation Steps	Keyboard focus or touch screen swiping falls on an element that is hidden or empty.

CONFIDENTIAL

Issue 14 | Control text lacks 4.5:1 contrast ratio on hover or focus	
WCAG 2.2 Criterion	1.4.3 Contrast (Minimum)
Conformance Level	AA
Impact Rating	Serious/High
Test URL(s)	https://www.centillioncap.com/index.php
Total Occurrences	44
Element Location	https://www.centillioncap.com/index.php (44 instances)
Description	The contrast ratio between a control's text and its background is not at least 4.5:1 on hover and/or on focus
User Impact	This is a serious accessibility barrier that causes significant difficulty for users navigating with assistive technologies.
Visual Evidence	

Remediation Steps	The contrast ratio between a control's text and its background is not at least 4.5:1 on hover and/or on focus

Issue 15 | Image of text is used instead of real text	
WCAG 2.2 Criterion	1.4.5 Images of Text
Conformance Level	AA
Impact Rating	Serious/High
Test URL(s)	https://www.centillioncap.com/index.php
Total Occurrences	2
Element Location	https://www.centillioncap.com/index.php (2 instances)
Description	The image contains embedded text.
User Impact	This is a serious accessibility barrier that causes significant difficulty for users navigating with assistive technologies.
Visual Evidence	
Remediation Steps	The image contains embedded text.

Issue 16 | The decorative image is not hidden from screen readers	
WCAG 2.2 Criterion	1.1.1 Non-text Content
Conformance Level	A
Impact Rating	Moderate/Medium
Test URL(s)	https://www.centillioncap.com/index.php
Total Occurrences	10
Element Location	https://www.centillioncap.com/index.php (10 instances)
Description	The decorative image is not hidden from screen readers.
User Impact	This issue causes frustration or reduces efficiency for users with disabilities but does not entirely block task completion.
Visual Evidence	



CONFI

Remediation Steps	The decorative image is not hidden from screen readers.

11. Risk Evaluation and Conclusion

Severity	Count	Action Required
Blocker / Critical	**6**	Immediate remediation required
Serious / High	**9**	Immediate remediation required
Moderate / Medium	**1**	Timely remediation required
Minor / Low	**0**	No issues identified

TOTAL	16	Overall Risk Exposure: High — 10 WCAG criteria fail — 16 unique issues identified

The application currently presents a high-risk profile due to critical blockers in keyboard navigation and visual focus indicators. These barriers prevent users with motor and visual disabilities from navigating the site or completing core tasks like the IPO application or contact forms. Immediate remediation of the 6 Blocker and 9 Serious issues is required to meet legal and regulatory standards.

12. Recommendations

Based on the full WCAG 2.2 assessment findings, the following prioritized remediation plan is recommended:

- **Critical: Restore Keyboard Operability (SC 2.1.1, 2.4.7)**
  - Implement a highly visible CSS focus indicator for all interactive elements (buttons, links, inputs) to ensure keyboard users can navigate.
  - Remediate all elements that currently do not respond to "Enter" or "Space" keys.
- **Critical: Fix Alternative Text (SC 1.1.1)**
  - Add descriptive alt text to the 6 informative images on the homepage and provide accessible names for IPO-related imagery.
- **Serious: Remediation of Contrast (SC 1.4.3)**
  - Update the CSS for the 'Contact Us' and 'Homepage' to ensure all text meets the minimum 4.5:1 contrast ratio, specifically addressing the identified 2.32:1 and 2.73:1 instances.
- **Serious: Correct Semantic Markup (SC 1.3.1, 4.1.2)**
  - Replace visual-only headings with semantic <h1>-<h6> tags and ensure all <iframe> elements have unique, descriptive titles.
- **Moderate: Mobile & UX Improvements (SC 1.4.4, 2.5.8)**
  - Remove user-scalable=no from the viewport meta tag to allow pinch-zooming on mobile devices.
  - Increase the tap target size of social media icons to at least 24×24 CSS pixels.

Ongoing Best Practices

Adopt an Accessibility-First Design approach integrating WCAG 2.2 requirements into the design and development lifecycle. Implement semantic HTML, WAI-ARIA, and automated accessibility testing in CI/CD pipelines. Conduct WCAG 2.2 re-assessments annually or after significant code changes. Train content authors and developers on accessibility requirements.

Prepared By

Sanket Milind Sapate

IAAP CPACC Certified Professional

Date: 29 April 2026

Organisation: Nishaj Infosolutions Pvt Ltd.

Email: office@nishajinfosolutions.com | Phone: +91 7678252326

SANKET MILIND SAPATE

Digitally signed by SANKET MILIND SAPATE
Date: 2026.04.29 11:10:12 +05'30'

CONFIDENTIAL

— End of Report —

CONFIDENTIAL